




DETAILED BREAKDOWN

150cc CARBURETOR (15856)

(substitute for p/n 14925)



View from driver side (under dump bed)



View from passenger side (under dump bed)

